σ vs. E for ^{70}Cu(n,tot.)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,el.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,nonel.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,inel.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,2n)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,n$_1$)

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,ncont.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,γ)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,p)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,tot.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,α)

Correlation Matrix

σ vs. E for ^{70}Cu(n,el.)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,el.)

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,el.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,nonel.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,el.)

Δσ/σ vs. E for ^{70}Cu(n,inel.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,el.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,2n)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,el.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,n$_1$)

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,el.)

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,ncont.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,el.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,γ)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,el.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,p)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,el.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,α)

Correlation Matrix

σ vs. E for ^{70}Cu(n,nonel.)

Δσ/σ vs. E for ^{70}Cu(n,nonel.)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,nonel.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,inel.)

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,nonel.)

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,2n)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,nonel.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,n$_1$)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,nonel.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,ncont.)

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,nonel.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,γ)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,nonel.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,p)

Correlation Matrix

Δσ/σ vs. E for ⁷⁰Cu(n,nonel.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ⁷⁰Cu(n,α)

Correlation Matrix

σ vs. E for ^{70}Cu(n,inel.)

Δσ/σ vs. E for ^{70}Cu(n,inel.)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

σ vs. E for ^{70}Cu(n,2n)

Δσ/σ vs. E for ^{70}Cu(n,2n)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,2n)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,n$_1$)

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,2n)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,ncont.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,2n)

Δσ/σ vs. E for ^{70}Cu(n,γ)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,2n)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,p)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,2n)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,α)

Correlation Matrix

σ vs. E for ^{70}Cu(n,3n)

Δσ/σ vs. E for ^{70}Cu(n,3n)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Correlation Matrix

σ vs. E for ^{70}Cu(n,nα)

Δσ/σ vs. E for ^{70}Cu(n,nα)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

σ vs. E for ^{70}Cu(n,2nα)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Δσ/σ vs. E for ^{70}Cu(n,2nα)

Correlation Matrix

σ vs. E for ^{70}Cu(n,np)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,np)

Correlation Matrix

σ vs. E for ^{70}Cu(n,nd)

Δσ/σ vs. E for ^{70}Cu(n,nd)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

σ vs. E for ^{70}Cu(n,nt)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,nt)

Correlation Matrix

σ vs. E for ^{70}Cu(n,2np)

Δσ/σ vs. E for ^{70}Cu(n,2np)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

σ vs. E for ^{70}Cu(n,n$_1$)

Δσ/σ vs. E for ^{70}Cu(n,n$_1$)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,n$_1$)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,ncont.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,n$_1$)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,γ)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,n$_1$)

Δσ/σ vs. E for ^{70}Cu(n,p)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,n$_1$)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,α)

Correlation Matrix

σ vs. E for ^{70}Cu(n,n$_2$)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,n$_2$)

Correlation Matrix

σ vs. E for ^{70}Cu(n,n$_3$)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,n$_3$)

Correlation Matrix

σ vs. E for ^{70}Cu(n,n$_4$)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Δσ/σ vs. E for ^{70}Cu(n,n$_4$)

Correlation Matrix

σ vs. E for ^{70}Cu(n,ncont.)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,ncont.)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,ncont.)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,γ)

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,ncont.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,p)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,ncont.)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,α)

Correlation Matrix

-1.0
-0.8
-0.6
-0.4
-0.2
0.0

1.0
0.8
0.6
0.4
0.2
0.0

σ vs. E for ^{70}Cu(n,γ)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,γ)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,γ)

Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,p)

Correlation Matrix

Δσ/σ vs. E for ^{70}Cu(n,γ)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

Δσ/σ vs. E for ^{70}Cu(n,α)

Correlation Matrix

σ vs. E for ^{70}Cu(n,p)

Δσ/σ vs. E for ^{70}Cu(n,p)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,p)

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for ^{70}Cu(n,α)

Correlation Matrix

σ vs. E for ^{70}Cu(n,d)

Δσ/σ vs. E for ^{70}Cu(n,d)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

σ vs. E for ^{70}Cu(n,t)

Δσ/σ vs. E for ^{70}Cu(n,t)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix

σ vs. E for ^{70}Cu(n,He3)

Δσ/σ vs. E for ^{70}Cu(n,He3)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Correlation Matrix

σ vs. E for ^{70}Cu(n,α)

Δσ/σ vs. E for ^{70}Cu(n,α)

Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix