Program EVALPLOT
(Version 2017-1)
by
Dermott E. Cullen
(Present Contact Information)
Dermott E. Cullen
1466 Hudson Way
Livermore, CA 94550
U.S.A.
Tele: 925-443-1911
E.Mail:redcullen1@comcast.net
Web:redcullen1.net/HOMEPAGE.NEW

Press Mouse Button to Start


MAT 3252
Major
32-Ge-79
293 Kelvin Cross Sections
Cross Section (barns)
Incident Energy (MeV)
Total
Elastic
Inelastic
(n,remainder)
(n,γ)
1
32-Ge-79


MAT 3252
Neutron Production
293 Kelvin Cross Sections
32-Ge-79
Cross Section (barns)
Incident Energy (MeV)
32-Ge-79
(n,2n)
(n,3n)
(n,n') α
(n,2n) α
(n,3n) α
(n,n') p


MAT 3252
Neutron Production
293 Kelvin Cross Sections
32-Ge-79
(n,n') d
(n,n') t
(n,n') He-3
(n,4n)
(n,2n) p
(n,3n) p
Cross Section (barns)
Incident Energy (MeV)
3
32-Ge-79


MAT 3252
Charged Particle
293 Kelvin Cross Sections
32-Ge-79
Cross Section (barns)
Incident Energy (MeV)
(n,n') α
(n,2n) α
(n,3n) α
(n,n') p
(n,n') d
(n,n') t
(n,n') He-3
(n,2n) p
4
32-Ge-79


MAT 3252
Charged Particle
293 Kelvin Cross Sections
32-Ge-79
(n,3n) p
(n,p)
(n,d)
(n,t)
(n,He-3)
(n,α)
(n,2p)
Cross Section (barns)
Incident Energy (MeV)
5
32-Ge-79


MAT 3252
Particle Production
293 Kelvin Cross Sections
32-Ge-79
Hydrogen Production
Deuterium Production
Tritium Production
He-3 Production
He-4 Production
Cross Section (barns)
Incident Energy (MeV)
6
32-Ge-79


MAT 3252
(n,n') Level
293 Kelvin Cross Sections
32-Ge-79
Inelastic
MT= 51 (n,n') Level
MT= 52 (n,n') Level
MT= 53 (n,n') Level
MT= 54 (n,n') Level
MT= 55 (n,n') Level
MT= 56 (n,n') Level
MT= 57 (n,n') Level
MT= 58 (n,n') Level
MT= 59 (n,n') Level
MT= 60 (n,n') Level
Cross Section (barns)
Incident Energy (MeV)
7
32-Ge-79


MAT 3252
(n,n') Level
293 Kelvin Cross Sections
32-Ge-79
Cross Section (barns)
Incident Energy (MeV)
MT= 61 (n,n') Level
MT= 62 (n,n') Level
MT= 63 (n,n') Level
MT= 64 (n,n') Level
MT= 65 (n,n') Level
MT= 66 (n,n') Level
MT= 67 (n,n') Level
MT= 68 (n,n') Level
MT= 69 (n,n') Level
MT= 70 (n,n') Level
MT= 71 (n,n') Level
8
32-Ge-79


MAT 3252
(n,n') Level
293 Kelvin Cross Sections
32-Ge-79
Cross Section (barns)
Incident Energy (MeV)
MT= 72 (n,n') Level
MT= 73 (n,n') Level
MT= 74 (n,n') Level
MT= 75 (n,n') Level
MT= 76 (n,n') Level
MT= 77 (n,n') Level
MT= 78 (n,n') Level
MT= 79 (n,n') Level
MT= 80 (n,n') Level
(n,n') Continuum
9
32-Ge-79


MAT 3252
(n,p) Levels
32-Ge-79
293 Kelvin Cross Sections
(n,p)
Cross Section (barns)
Incident Energy (MeV)
32-Ge-79


MAT 3252
(n,d) Levels
32-Ge-79
293 Kelvin Cross Sections
(n,d)
Cross Section (barns)
Incident Energy (MeV)
11
32-Ge-79

293 Kelvin Cross Sections




MAT 3252
(n,He3) Levels
32-Ge-79
293 Kelvin Cross Sections
(n,He-3)
Cross Section (barns)
10-6
10-8
10-10
10-12
5
2
3
4
5
6
7
8
9
10 2
2
13
Incident Energy (MeV)
32-Ge-79


MAT 3252
(n,α) Levels
32-Ge-79
293 Kelvin Cross Sections
(n,α)
Cross Section (barns)
10^-4
10^-6
10^-8
10^-10
2
4
6
8
10^1
2
4
6
8
10^2
2
14
Incident Energy (MeV)
32-Ge-79


MAT 3252
Energy Release
Parameters
32-Ge-79
Kerma total (eV-barns)
Kerma elastic
Kerma non-elastic (all but mt2)
Kerma inelastic (mt51-91)
Kerma capture (mt102)
Total photon (eV-barns)
Total kinematic kerma (high limit)
Dpa total (eV-barns)
Dpa elastic (mt2)
Dpa inelastic (mt51-91)
Dpa disappearance (mt102 -120)
Parameters
10^18
10^15
10^12
10^9
10^6
10^3
10^-10
10^-8
10^-6
10^-4
10^-2
10^0
10^2
Incident Energy (MeV)
15
32-Ge-79


MAT 3252
Elastic
Legendre Coefficients
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9
Legendre (CM)
1.0
0.8
0.6
0.4
0.2
0.0
0
10
20
30
16
Incident Energy (MeV)
32-Ge-79


MAT 3252
Elastic
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
Legendre (CM)
0.25
0.20
0.15
0.10
0.05
0.00
5
10
15
20
25
30
17
Incident Energy (MeV)
32-Ge-79


MAT 3252
Elastic
Legendre Coefficients
32-Ge-79
X10^{-3}
1.0
0.8
0.6
0.4
0.2
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
10
15
20
25
30
18
Incident Energy (MeV)
32-Ge-79


MAT 3252
Elastic
Legendre Coefficients
32-Ge-79
0.0
X10-7
-0.5
-1.0
-1.5
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
15
20
25
30
19
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 51 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
20
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 51 (n,n') Level
Legendre Coefficients
32-Ge-79
0.015
0.010
0.005
0.000
-0.005
Legendre (CM)
P10
P11
P12
P13
P14
P15
P16
P17
P18
0
50
100
150
200
21
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 51 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-3
-0.2
-0.4
-0.6
-0.8
-1.0
-1.2
Legendre (CM)
50
100
150
200
22
Incident Energy (MeV)
32-Ge-79
P19
P20
P21
P22
P23
P24
P25
P26
P27


MAT 3252
MT= 51 (n,n') Level
Legendre Coefficients
32-Ge-79
0
X10-7
-1
-2
-3
Legendre (CM)
50
100
150
200
23
Incident Energy (MeV)
32-Ge-79
P28
P29
P30
P31
P32
P33
P34


MAT 3252
MT= 52 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
24
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 52 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.020
0.015
0.010
0.005
0.000
-0.005
Legendre (CM)
0
50
100
150
200
25
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 52 (n,n') Level
Legendre Coefficients
32-Ge-79
X10 -4
4
3
2
1
0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
26
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 52 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-7
1.5
1.0
0.5
0.0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
27
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 53 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
28
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9


MAT 3252
MT= 53 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
0
50
100
150
200
29
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 53 (n,n') Level
Legendre Coefficients
32-Ge-79
X10 -3
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
30
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 53 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-7
3
2
1
0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
31
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 54 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
32
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9


MAT 3252
MT= 54 (n,n') Level
Legendre Coefficients
32-Ge-79
0.015
0.010
0.005
0.000
-0.005
Legendre (CM)
P10
P11
P12
P13
P14
P15
P16
P17
P18
0
50
100
150
200
33
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 54 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-3
-0.2
-0.4
-0.6
-0.8
-1.0
Legendre (CM)
50
100
150
200
34
Incident Energy (MeV)
32-Ge-79
P19
P20
P21
P22
P23
P24
P25
P26
P27


MAT 3252
MT= 54 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-7
-0.5
-1.0
-1.5
-2.0
-2.5
Legendre (CM)
50
100
150
200
35
Incident Energy (MeV)
32-Ge-79
P28
P29
P30
P31
P32
P33
P34


MAT 3252
MT= 55 (n,n') Level
Legendre Coefficients
32-Ge-79
0.5
0.4
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
36
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 55 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
0
50
100
150
200
37
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 55 (n,n') Level
Legendre Coefficients
32-Ge-79
X10^-3
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
50
100
150
200
Incident Energy (MeV)
38
32-Ge-79
P19
P20
P21
P22
P23
P24
P25
P26
P27


MAT 3252
MT= 55 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-7
3
2
1
0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
39
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 56 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.3
0.2
0.1
0.0
0
50
100
150
200
40
Incident Energy (MeV)
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9


MAT 3252
MT= 56 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.06
0.04
0.02
0.00
-0.02
-0.04
Legendre (CM)
0
50
100
150
200
41
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 56 (n,n') Level
Legendre Coefficients
32-Ge-79
0.000
0.000
-0.002
-0.003
Legendre (CM)
50
100
150
200
Incident Energy (MeV)
42
32-Ge-79
P19
P20
P21
P22
P23
P24
P25
P26
P27


MAT 3252
MT= 56 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-7
0
-1
-2
-3
-4
Legendre (CM)
50
100
150
200
43
Incident Energy (MeV)
32-Ge-79
P28
P29
P30
P31
P32
P33
P34


MAT 3252
MT= 57 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
44
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9


MAT 3252
MT= 57 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
0
50
100
150
200
45
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 57 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
1.5
1.0
0.5
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
46
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 57 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
2
1
0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
47
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 58 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
48
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 58 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
0
50
100
150
200
49
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 58 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
1.5
1.0
0.5
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
50
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 58 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
3
2
1
0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
51
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 59 (n,n') Level
Legendre Coefficients
32-Ge-79
0.5
0.4
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
52
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 59 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
0
50
100
150
200
53
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 59 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
1.5
1.0
0.5
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
54
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 59 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-2
3
2
1
0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
55
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 60 (n,n') Level
Legendre Coefficients
32-Ge-79
0.5
0.4
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
56
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 60 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
0
50
100
150
200
57
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 60 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
1.5
1.0
0.5
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
58
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 60 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-7
2.5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
59
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 61 (n,n') Level
Legendre Coefficients
32-Ge-79
0.5
0.4
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
60
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 61 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
0
50
100
150
200
61
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 61 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
1.5
1.0
0.5
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
62
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 61 (n,n') Level
Legendre Coefficients
32-Ge-79
X10^-7
2.5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
63
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 62 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
64
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 62 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.020
0.015
0.010
0.005
0.000
Legendre (CM)
0
50
100
150
200
65
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 62 (n,n') Level
Legendre Coefficients
32-Ge-79
X10 −4
4
3
2
1
0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
66
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 62 (n,n') Level
Legendre Coefficients
32-Ge-79
X10^-7
1.2
1.0
0.8
0.6
0.4
0.2
0.0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
67
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 63 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
68
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 63 (n,n') Level
Legendre Coefficients
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
0.000
0.000
0.000
0.000
0.000
Legendre (CM)
50
100
150
200
69
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 63 (n,n') Level
Legendre Coefficients
32-Ge-79
2.0
X10 −6
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
70
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 64 (n,n') Level
Legendre Coefficients
32-Ge-79
0.5
0.4
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
71
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 64 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
50
100
150
200
72
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 64 (n,n') Level
Legendre Coefficients
32-Ge-79
X10^-3
1.5
1.0
0.5
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
73
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 64 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-7
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
50
100
150
200
74
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 65 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
75
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 65 (n,n') Level
Legendre Coefficients
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
0.020
0.015
0.010
0.005
0.000
Legendre (CM)
50
100
150
200
76
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 65 (n,n') Level
Legendre Coefficients
32-Ge-79
X10^-5
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
77
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 66 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
78
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 3252
MT= 66 (n,n') Level
Legendre Coefficients
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
0.020
0.015
0.010
0.005
0.000
Legendre (CM)
50
100
150
200
79
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 66 (n,n') Level
Legendre Coefficients
32-Ge-79
X10^-5
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
80
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 67 (n,n') Level
Legendre Coefficients
32-Ge-79
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
81
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 67 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.06
0.04
0.02
0.00
-0.02
Legendre (CM)
0
50
100
150
200
82
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 67 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-3
-0.5
-1.0
-1.5
-2.0
Legendre (CM)
50
100
150
200
83
Incident Energy (MeV)
32-Ge-79
P19
P20
P21
P22
P23
P24
P25
P26
P27


MAT 3252
MT= 67 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-7
-0.5
-1.0
-1.5
-2.0
-2.5
Legendre (CM)
50
100
150
200
84
Incident Energy (MeV)
32-Ge-79
P28
P29
P30
P31
P32
P33
P34


MAT 3252
MT= 68 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.3
0.2
0.1
0.0
-0.1
50
100
150
200
85
Incident Energy (MeV)
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 3252
MT= 68 (n,n') Level
Legendre Coefficients
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
0.000
0.000
0.000
0.000
Legendre (CM)
50
100
150
200
86
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 68 (n,n') Level
Legendre Coefficients
32-Ge-79
X10^-6
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
87
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 69 (n,n') Level
Legendre Coefficients
32-Ge-79
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
50
100
150
200
88
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 69 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.06
0.04
0.02
0.00
-0.02
Legendre (CM)
50
100
150
200
89
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 69 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-3
-0.5
-1.0
-1.5
-2.0
Legendre (CM)
50
100
150
200
90
Incident Energy (MeV)
32-Ge-79
P19
P20
P21
P22
P23
P24
P25
P26
P27


MAT 3252
MT= 69 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-7
-0.5
-1.0
-1.5
-2.0
-2.5
Legendre (CM)
50
100
150
200
91
Incident Energy (MeV)
32-Ge-79
P28
P29
P30
P31
P32
P33
P34


MAT 3252
MT= 70 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
50
100
150
200
92
Incident Energy (MeV)
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 3252
MT= 70 (n,n') Level
Legendre Coefficients
32-Ge-79
0.004
0.002
0.000
-0.002
Legendre (CM)
50
100
150
200
93
Incident Energy (MeV)
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 3252
MT= 70 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-5
-0.5
-1.0
-1.5
-2.0
-2.5
Legendre (CM)
50
100
150
200
94
Incident Energy (MeV)
32-Ge-79
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 3252
MT= 71 (n,n') Level
Legendre Coefficients
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
50
100
150
200
95
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 71 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.03
0.02
0.01
0.00
-0.01
-0.02
Legendre (CM)
50
100
150
200
96
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 71 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
1.2
0.8
0.4
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
50
100
150
200
97
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 71 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-7
1.5
1.0
0.5
0.0
Legendre (CM)
50
100
150
200
98
Incident Energy (MeV)
32-Ge-79
P28
P29
P30
P31
P32
P33
P34


MAT 3252
MT= 72 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
99
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 72 (n,n') Level
Legendre Coefficients
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
0.020
0.015
0.010
0.005
0.000
Legendre (CM)
50
100
150
200
100
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 72 (n,n') Level
Legendre Coefficients
32-Ge-79
1.5
X10-5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
101
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 73 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
102
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 73 (n,n') Level
Legendre Coefficients
32-Ge-79
0.000
-0.002
-0.004
-0.006
Legendre (CM)
50
100
150
200
103
Incident Energy (MeV)
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 3252
MT= 73 (n,n') Level
Legendre Coefficients
32-Ge-79
0
X10^-6
-1
-2
-3
-4
-5
Legendre (CM)
50
100
150
200
104
Incident Energy (MeV)
32-Ge-79
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 3252
MT= 74 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.2
0.1
0.0
-0.1
50
100
150
200
105
Incident Energy (MeV)
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10


MAT 3252
MT= 74 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-3
1.5
1.0
0.5
0.0
-0.5
Legendre (CM)
P11
P12
P13
P14
P15
P16
P17
P18
P19
P20
50
100
150
200
106
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 74 (n,n') Level
Legendre Coefficients
32-Ge-79
X10-1
0
-2
-4
-6
Legendre (CM)
50
100
150
200
107
Incident Energy (MeV)
32-Ge-79
P21
P22
P23
P24
P25
P26
P27
P28
P29
P30


MAT 3252
MT= 75 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
108
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 75 (n,n') Level
Legendre Coefficients
32-Ge-79
0.004
0.002
0.000
-0.002
Legendre (CM)
50
100
150
200
109
Incident Energy (MeV)
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 3252
MT= 75 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-5
-0.5
-1.0
-1.5
-2.0
-2.5
Legendre (CM)
50
100
150
200
110
Incident Energy (MeV)
32-Ge-79
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 3252
MT= 76 (n,n') Level
Legendre Coefficients
32-Ge-79
0.3
0.2
0.1
0.0
Legendre (CM)
50
100
150
200
111
Incident Energy (MeV)
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9


MAT 3252
MT= 76 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.06
0.04
0.02
0.00
-0.02
Legendre (CM)
50
100
150
200
112
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 76 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-3
-0.5
-1.0
-1.5
-2.0
Legendre (CM)
50
100
150
200
113
Incident Energy (MeV)
32-Ge-79
P19
P20
P21
P22
P23
P24
P25
P26
P27


MAT 3252
MT= 76 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-7
-0.5
-1.0
-1.5
-2.0
Legendre (CM)
50
100
150
200
114
Incident Energy (MeV)
32-Ge-79
P28
P29
P30
P31
P32
P33
P34


MAT 3252
MT= 77 (n,n') Level
Legendre Coefficients
32-Ge-79
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
50
100
150
200
115
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 77 (n,n') Level
Legendre Coefficients
32-Ge-79
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.06
0.04
0.02
0.00
-0.02
Legendre (CM)
50
100
150
200
116
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 77 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-3
-0.5
-1.0
-1.5
-2.0
Legendre (CM)
50
100
150
200
117
Incident Energy (MeV)
32-Ge-79
P19
P20
P21
P22
P23
P24
P25
P26
P27


MAT 3252
MT= 77 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-7
-0.5
-1.0
-1.5
-2.0
Legendre (CM)
50
100
150
200
118
Incident Energy (MeV)
32-Ge-79
P28
P29
P30
P31
P32
P33
P34


MAT 3252
MT= 78 (n,n') Level
Legendre Coefficients
32-Ge-79
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
119
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 78 (n,n') Level
Legendre Coefficients
32-Ge-79
0.004
0.002
0.000
-0.002
Legendre (CM)
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
50
100
150
200
120
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 78 (n,n') Level
Legendre Coefficients
32-Ge-79
0.0
X10^-5
-0.5
-1.0
-1.5
-2.0
Legendre (CM)
50
100
150
200
121
Incident Energy (MeV)
32-Ge-79
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 3252
MT= 79 (n,n') Level
Legendre Coefficients
32-Ge-79
0.4
0.3
0.2
0.1
0.0
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
50
100
150
200
122
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 79 (n,n') Level
Legendre Coefficients
32-Ge-79
0.000
-0.002
-0.004
-0.006
Legendre (CM)
50
100
150
200
123
Incident Energy (MeV)
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 3252
MT= 79 (n,n') Level
Legendre Coefficients
32-Ge-79
X10^-6
0
-1
-2
-3
-4
-5
Legendre (CM)
50
100
150
200
124
Incident Energy (MeV)
32-Ge-79
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 3252
MT= 80 (n,n') Level
Legendre Coefficients
32-Ge-79
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
50
100
150
200
125
Incident Energy (MeV)
32-Ge-79


MAT 3252
MT= 80 (n,n') Level
Legendre Coefficients
32-Ge-79
0.010
0.005
0.000
-0.005
-0.010
-0.015
Legendre (CM)
50
100
150
200
126
Incident Energy (MeV)
32-Ge-79
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 3252
MT= 80 (n,n') Level
Legendre Coefficients
32-Ge-79
X10 -5
3
2
1
0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
127
Incident Energy (MeV)
32-Ge-79


MAT 3252
Inelastic
32-Ge-79
Radionuclide Production Cross Section
32-Ge-79g
32-Ge-79m1
Cross Section (barns)
Incident Energy (MeV)
128
32-Ge-79


MAT 3252
(n,3n)
32-Ge-79
Radionuclide Production Cross Section
32-Ge-77g
32-Ge-77m1
Cross Section (barns)
10^-1
10^-2
10^-3
10^-4
5
2
3
4
6
7
8
9
10^2
Incident Energy (MeV)
129
32-Ge-79


MAT 3252
(n,3n) α
32-Ge-79
Radionuclide Production Cross Section
30-Zn-73g
30-Zn-73m3
Cross Section (barns)
10^-8
10^-10
10^-12
10^-14
5
3
4
5
6
7
8
9
10^2
2
130
Incident Energy (MeV)
32-Ge-79


MAT 3252
(n,He-3)
32-Ge-79
Radionuclide Production Cross Section
30-Zn-77g
30-Zn-77m2
Cross Section (barns)
10^-6
10^-8
10^-10
10^-12
2
3
4
5
6
7
8
9
10^2
2
131
Incident Energy (MeV)
32-Ge-79