


Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).




Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).




Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).




Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix









Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix









Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.






Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).






Correlation Matrix