Program EVALPLOT
(Version 2021-1)
by
Dermott E. Cullen
(Present Contact Information)
Dermott E. Cullen
1466 Hudson Way
Livermore, CA 94550
U.S.A.
Tele: 925-443-1911
E.Mail:redcullen1@comcast.net
Web:redcullen1.net/HOMEPAGE.NEW

Press Mouse Button to Start


MAT 2922
Neutron Major
293 Kelvin Cross Sections
29-Cu-62
Cross Section (barns)
Incident Energy (MeV)
Total
Elastic
Nonelastic
Inelastic
(n,2n)
(n,3n)
(n,γ)
1
29-Cu-62


MAT 2922
Neutron Absorption
293 Kelvin Cross Sections
29-Cu-62
Cross Section (barns)
Incident Energy (MeV)
29-Cu-62
(n,2n) d
(n,2n)
(n,3n)
(n,n') α
(n,2n) α
(n,n') p
(n,n') 2α
(n,n') d
(n,n') t
(n,n') He-3
(n,2n) p


MAT 2922
Neutron Absorption
293 Kelvin Cross Sections
29-Cu-62
Cross Section (barns)
Incident Energy (MeV)
(n,3n) p
(n,2n) p
(n,n') p α
(n,γ)
(n,p)
(n,d)
(n,t)
(n,He-3)
(n,α)
(n,2α)
(n,2p)
3
29-Cu-62


MAT 2922
Neutron Absorption
293 Kelvin Cross Sections
29-Cu-62
(n,p) α
(n,p) d
(n,p) t
(n,d) α
Hydrogen Production
Deuterium Production
Tritium Production
He-3 Production
He-4 Production
Cross Section (barns)
10^4
10^2
10^0
10^-2
10^-4
10^-10
10^-8
10^-6
10^-4
10^-2
10^0
10^2
Incident Energy (MeV)
4
29-Cu-62


MAT 2922
Charged Particle
293 Kelvin Cross Sections
29-Cu-62
Cross Section (barns)
Incident Energy (MeV)
29-Cu-62
(n,n') α
(n,2n) α
(n,n') p
(n,n') d
(n,n') t
(n,n') He-3
(n,2n) p
(n,3n) p
(n,p)
(n,d)


MAT 2922
Charged Particle
293 Kelvin Cross Sections
29-Cu-62
Cross Section (barns)
Incident Energy (MeV)
(n,n') α
(n,t)
(n,He-3)
(n,α)
(n,2α)
(n,2p)
(n,p) α
(n,p) d
(n,p) t
(n,d) α
6
29-Cu-62


MAT 2922
Particle Production
293 Kelvin Cross Sections
29-Cu-62
Hydrogen Production
Deuterium Production
Tritium Production
He-3 Production
He-4 Production
Cross Section (barns)
Incident Energy (MeV)
7
29-Cu-62


MAT 2922
(n,n') Levels
293 Kelvin Cross Sections
29-Cu-62
Inelastic
MT= 51 (n,n') Level
MT= 52 (n,n') Level
MT= 53 (n,n') Level
MT= 54 (n,n') Level
MT= 55 (n,n') Level
MT= 56 (n,n') Level
MT= 57 (n,n') Level
MT= 58 (n,n') Level
Cross Section (barns)
Incident Energy (MeV)
8
29-Cu-62


MAT 2922
(n,n') Levels
293 Kelvin Cross Sections
29-Cu-62
Inelastic
MT= 59 (n,n') Level
MT= 60 (n,n') Level
MT= 61 (n,n') Level
MT= 62 (n,n') Level
MT= 63 (n,n') Level
MT= 64 (n,n') Level
MT= 65 (n,n') Level
MT= 66 (n,n') Level
Cross Section (barns)
Incident Energy (MeV)
9
29-Cu-62


MAT 2922
(n,n') Levels
293 Kelvin Cross Sections
29-Cu-62
Inelastic
MT= 67 (n,n') Level
MT= 68 (n,n') Level
MT= 69 (n,n') Level
MT= 70 (n,n') Level
MT= 71 (n,n') Level
MT= 72 (n,n') Level
MT= 73 (n,n') Level
MT= 74 (n,n') Level
Cross Section (barns)
Incident Energy (MeV)
29-Cu-62


MAT 2922
(n,n') Levels
29-Cu-62
293 Kelvin Cross Sections
Cross Section (barns)
Incident Energy (MeV)
Inelastic
MT= 75 (n,n') Level
MT= 76 (n,n') Level
MT= 77 (n,n') Level
MT= 78 (n,n') Level
MT= 79 (n,n') Level
MT= 80 (n,n') Level
(n,n') Continuum
11
29-Cu-62


MAT 2922
(n,p) Levels
29-Cu-62
293 Kelvin Cross Sections
Cross Section (barns)
10^4
10^3
10^2
10^1
10^0
10^-1
5
(n,p)
10^-10
10^-8
10^-6
10^-4
10^-2
10^0
10^2
Incident Energy (MeV)
12
29-Cu-62


MAT 2922
(n,d) Levels
29-Cu-62
293 Kelvin Cross Sections
(n,d)
Cross Section (barns)
10-2
10-4
10-6
10-8
5
4 5 6 7 8 9 10 1 2 3 4 5 6 7 8 9 10 2 2
Incident Energy (MeV)
13
29-Cu-62


MAT 2922
(n,t) Levels
29-Cu-62
293 Kelvin Cross Sections
(n,t)
Cross Section (barns)
Incident Energy (MeV)
14
29-Cu-62


MAT 2922
(n,He3) Levels
29-Cu-62
293 Kelvin Cross Sections
(n,He-3)
Cross Section (barns)
Incident Energy (MeV)
15
29-Cu-62


MAT 2922
(n,α) Levels
29-Cu-62
293 Kelvin Cross Sections
Cross Section (barns)
5
5
10-2
5
5
10-4
5
5
10-6
5
5
10-8
5
(n,α)
(n,2α)
10-10
10-8
10-6
10-4
10-2
100
102
16
Incident Energy (MeV)
29-Cu-62


MAT 2922
Elastic
Legendre Coefficients
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
Legendre (CM)
1.2
1.0
0.8
0.6
0.4
0.2
0.0
0
10
20
30
17
Incident Energy (MeV)
29-Cu-62


MAT 2922
Elastic
Legendre Coefficients
29-Cu-62
P10
P11
P12
P13
P14
P15
P16
P17
P18
0.20
0.15
0.10
0.05
0.00
Legendre (CM)
5
10
15
20
25
30
18
Incident Energy (MeV)
29-Cu-62


MAT 2922
Elastic
Legendre Coefficients
29-Cu-62
X10^-4
4
3
2
1
0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
P27
10
15
20
25
30
19
Incident Energy (MeV)
29-Cu-62


MAT 2922
Elastic
Legendre Coefficients
29-Cu-62
0.0
X10^-7
-0.2
-0.4
-0.6
-0.8
-1.0
-1.2
Legendre (CM)
P28
P29
P30
P31
P32
P33
P34
15
20
25
30
20
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 51 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
21
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 2922
MT= 51 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
0
50
100
150
200
22
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 51 (n,n') Level
Legendre Coefficients
29-Cu-62
X10 -5
2.5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
50
100
150
200
23
Incident Energy (MeV)
29-Cu-62
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 2922
MT= 52 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
24
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 2922
MT= 52 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
0
50
100
150
200
25
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 52 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
26
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 53 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
27
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 53 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
0
50
100
150
200
Incident Energy (MeV)
28
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 53 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
29
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 54 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
30
Incident Energy (MeV)
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 2922
MT= 54 (n,n') Level
Legendre Coefficients
29-Cu-62
0.004
0.003
0.002
0.001
0.000
-0.001
Legendre (CM)
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
0
50
100
150
200
31
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 54 (n,n') Level
Legendre Coefficients
29-Cu-62
1.0
X10^-5
0.8
0.6
0.4
0.2
0.0
Legendre (CM)
50
100
150
200
32
Incident Energy (MeV)
29-Cu-62
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 2922
MT= 55 (n,n') Level
Legendre Coefficients
29-Cu-62
0.10
0.08
0.06
0.04
0.02
0.00
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
0
50
100
150
200
33
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 55 (n,n') Level
Legendre Coefficients
29-Cu-62
X10^-4
0
-2
-4
-6
Legendre (CM)
P9
P10
P11
P12
P13
P14
P15
P16
0
50
100
150
200
34
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 55 (n,n') Level
Legendre Coefficients
29-Cu-62
X10^-8
5
4
3
2
1
0
Legendre (CM)
50
100
150
200
35
Incident Energy (MeV)
29-Cu-62
P17
P18
P19
P20
P21
P22
P23
P24


MAT 2922
MT= 56 (n,n') Level
Legendre Coefficients
29-Cu-62
0.15
0.10
0.05
0.00
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
36
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 56 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-3
1.5
1.0
0.5
0.0
Legendre (CM)
P10
P11
P12
P13
P14
P15
P16
P17
P18
0
50
100
150
200
37
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 56 (n,n') Level
Legendre Coefficients
29-Cu-62
X10+75
1.0
0.5
0.0
Legendre (CM)
50
100
150
200
38
Incident Energy (MeV)
29-Cu-62
P19
P20
P21
P22
P23
P24
P25
P26


MAT 2922
MT= 57 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.15
0.10
0.05
0.00
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
39
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 57 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-3
1.5
1.0
0.5
0.0
Legendre (CM)
P10
P11
P12
P13
P14
P15
P16
P17
P18
0
50
100
150
200
40
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 57 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-7
1.5
1.0
0.5
0.0
Legendre (CM)
P19
P20
P21
P22
P23
P24
P25
P26
50
100
150
200
41
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 58 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
42
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 2922
MT= 58 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
Incident Energy (MeV)
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 58 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
44
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 59 (n,n') Level
Legendre Coefficients
29-Cu-62
0.10
0.08
0.06
0.04
0.02
0.00
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
0
50
100
150
200
45
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 59 (n,n') Level
Legendre Coefficients
29-Cu-62
X10^-4
0
-2
-4
-6
Legendre (CM)
P9
P10
P11
P12
P13
P14
P15
P16
0
50
100
150
200
46
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 59 (n,n') Level
Legendre Coefficients
29-Cu-62
X10^-8
5
4
3
2
1
0
Legendre (CM)
50
100
150
200
47
Incident Energy (MeV)
29-Cu-62
P17
P18
P19
P20
P21
P22
P23
P24


MAT 2922
MT= 60 (n,n') Level
Legendre Coefficients
29-Cu-62
0.10
0.08
0.06
0.04
0.02
0.00
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
0
50
100
150
200
48
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 60 (n,n') Level
Legendre Coefficients
29-Cu-62
0
X10^-4
-2
-4
-6
Legendre (CM)
P9
P10
P11
P12
P13
P14
P15
P16
0
50
100
150
200
49
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 60 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-8
5
4
3
2
1
0
Legendre (CM)
50
100
150
200
50
Incident Energy (MeV)
29-Cu-62
P17
P18
P19
P20
P21
P22
P23
P24


MAT 2922
MT= 61 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
51
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 61 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
52
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 61 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
53
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 62 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
54
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 2922
MT= 62 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
55
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 62 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
56
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 63 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
57
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 2922
MT= 63 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
58
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 63 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
59
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 64 (n,n') Level
Legendre Coefficients
29-Cu-62
0.10
0.08
0.06
0.04
0.02
0.00
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
0
50
100
150
200
60
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 64 (n,n') Level
Legendre Coefficients
29-Cu-62
0
X10^-4
-2
-4
-6
Legendre (CM)
P9
P10
P11
P12
P13
P14
P15
P16
0
50
100
150
200
61
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 64 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-8
5
4
3
2
1
0
Legendre (CM)
50
100
150
200
62
Incident Energy (MeV)
29-Cu-62
P17
P18
P19
P20
P21
P22
P23
P24


MAT 2922
MT= 65 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
63
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 65 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
Incident Energy (MeV)
64
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 65 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
65
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 66 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
66
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 66 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
67
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 66 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
68
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 67 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
69
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 67 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
70
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 67 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
71
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 68 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
72
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 68 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
73
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 68 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-2
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
50
100
150
200
74
Incident Energy (MeV)
29-Cu-62
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 2922
MT= 69 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
75
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 69 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
Incident Energy (MeV)
76
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 69 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-2
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
50
100
150
200
77
Incident Energy (MeV)
29-Cu-62
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 2922
MT= 70 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
78
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 70 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
79
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 70 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-2
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
80
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 71 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.10
0.08
0.06
0.04
0.02
0.00
0
50
100
150
200
Incident Energy (MeV)
81
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8


MAT 2922
MT= 71 (n,n') Level
Legendre Coefficients
29-Cu-62
X10^-4
0
-2
-4
-6
Legendre (CM)
P9
P10
P11
P12
P13
P14
P15
P16
0
50
100
150
200
82
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 71 (n,n') Level
Legendre Coefficients
29-Cu-62
X10^-8
5
4
3
2
1
0
Legendre (CM)
50
100
150
200
83
Incident Energy (MeV)
29-Cu-62
P17
P18
P19
P20
P21
P22
P23
P24


MAT 2922
MT= 72 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
84
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 2922
MT= 72 (n,n') Level
Legendre Coefficients
29-Cu-62
0.003
0.002
0.001
0.000
-0.001
Legendre (CM)
50
100
150
200
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
85
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 72 (n,n') Level
Legendre Coefficients
29-Cu-62
X10 -6
8
6
4
2
0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
86
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 73 (n,n') Level
Legendre Coefficients
29-Cu-62
0.10
0.08
0.06
0.04
0.02
0.00
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
0
50
100
150
200
87
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 73 (n,n') Level
Legendre Coefficients
29-Cu-62
X10^-5
0
-2
-4
-6
-8
Legendre (CM)
50
100
150
200
Incident Energy (MeV)
88
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 74 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
Incident Energy (MeV)
89
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11


MAT 2922
MT= 74 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
90
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 74 (n,n') Level
Legendre Coefficients
29-Cu-62
X10 -5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
91
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 75 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.15
0.10
0.05
0.00
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
92
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 75 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-3
1.5
1.0
0.5
0.0
Legendre (CM)
P10
P11
P12
P13
P14
P15
P16
P17
P18
0
50
100
150
200
93
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 75 (n,n') Level
Legendre Coefficients
29-Cu-62
X10-7
1.2
1.0
0.8
0.6
0.4
0.2
0.0
Legendre (CM)
50
100
150
200
P19
P20
P21
P22
P23
P24
P25
P26
94
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 76 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
95
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 76 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
96
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 76 (n,n') Level
Legendre Coefficients
29-Cu-62
X10 -5
2.0
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
97
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 77 (n,n') Level
Legendre Coefficients
29-Cu-62
P1
P2
P3
P4
P5
P6
P7
P8
0.02
0.01
0.00
-0.01
-0.02
-0.03
Legendre (CM)
0
50
100
150
200
98
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 77 (n,n') Level
Legendre Coefficients
29-Cu-62
X10^-4
3
2
1
0
Legendre (CM)
P9
P10
P11
P12
P13
P14
P15
P16
0
50
100
150
200
99
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 77 (n,n') Level
Legendre Coefficients
29-Cu-62
0
X10-7
-1
-2
-3
Legendre (CM)
50
100
150
200
100
Incident Energy (MeV)
29-Cu-62
P17
P18
P19
P20
P21
P22
P23
P24


MAT 2922
MT= 78 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
101
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 78 (n,n') Level
Legendre Coefficients
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22
0.04
0.02
0.00
-0.02
Legendre (CM)
50
100
150
200
102
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 78 (n,n') Level
Legendre Coefficients
29-Cu-62
0.0
X10^-5
-0.5
-1.0
-1.5
-2.0
-2.5
Legendre (CM)
50
100
150
200
103
Incident Energy (MeV)
29-Cu-62
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32


MAT 2922
MT= 79 (n,n') Level
Legendre Coefficients
29-Cu-62
0.20
0.15
0.10
0.05
0.00
Legendre (CM)
P1
P2
P3
P4
P5
P6
P7
P8
P9
0
50
100
150
200
104
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 79 (n,n') Level
Legendre Coefficients
29-Cu-62
0.004
0.003
0.002
0.001
0.000
Legendre (CM)
P10
P11
P12
P13
P14
P15
P16
P17
P18
0
50
100
150
200
105
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 79 (n,n') Level
Legendre Coefficients
29-Cu-62
0.0
X10-7
-0.2
-0.4
-0.6
-0.8
-1.0
-1.2
Legendre (CM)
50
100
150
200
106
Incident Energy (MeV)
29-Cu-62
P19
P20
P21
P22
P23
P24
P25
P26


MAT 2922
MT= 80 (n,n') Level
Legendre Coefficients
29-Cu-62
Legendre (CM)
0.5
0.4
0.3
0.2
0.1
0.0
0
50
100
150
200
P1
P2
P3
P4
P5
P6
P7
P8
P9
P10
P11
107
Incident Energy (MeV)
29-Cu-62


MAT 2922
MT= 80 (n,n') Level
Legendre Coefficients
29-Cu-62
0.010
0.005
0.000
-0.005
-0.010
Legendre (CM)
50
100
150
200
108
Incident Energy (MeV)
29-Cu-62
P12
P13
P14
P15
P16
P17
P18
P19
P20
P21
P22


MAT 2922
MT= 80 (n,n') Level
Legendre Coefficients
29-Cu-62
2.0
X10-5
1.5
1.0
0.5
0.0
Legendre (CM)
P23
P24
P25
P26
P27
P28
P29
P30
P31
P32
50
100
150
200
109
Incident Energy (MeV)
29-Cu-62


MAT 2922
(n,n') α
29-Cu-62
Radionuclide Production Cross Section
27-Co-58g
27-Co-58m1
Cross Section (barns)
Incident Energy (MeV)
110
29-Cu-62


MAT 2922
(n,2n) p
29-Cu-62
Radionuclide Production Cross Section
27-Co-60g
27-Co-60m1
Cross Section (barns)
Incident Energy (MeV)
111
29-Cu-62


MAT 2922
(n,He-3)
29-Cu-62
Radionuclide Production Cross Section
27-Co-60g
27-Co-60m1
Cross Section (barns)
Incident Energy (MeV)
112
29-Cu-62


MAT 2922
(n,p) d
29-Cu-62
Radionuclide Production Cross Section
27-Co-60g
27-Co-60m1
Cross Section (barns)
10^-4
10^-6
10^-8
10^-10
2
3
4
5
6
7
8
9
10^2
2
113
Incident Energy (MeV)
29-Cu-62