




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{tot.})$





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{tot.})$





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).




Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).




$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{tot.})$




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,p)$



Ordinate scale is %  
relative standard deviation.





Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{tot.})$



Correlation Matrix










Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{inel.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{el.})$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,p)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{el.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{nonel.})$





Correlation Matrix








$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{nonel.})$




Correlation Matrix










Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{nonel.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.





Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{nonel.})$



Correlation Matrix









Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Ordinate scale is %  
relative standard deviation.





Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{inel.})$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{inel.})$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n_1)$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n\text{cont.})$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Correlation Matrix








Ordinate scale is %  
relative standard deviation.

Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,p)$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\alpha)$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n)$




Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,3n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{66}\text{Cu}(n,3n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n\alpha)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{66}\text{Cu}(n,n\alpha)$




Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2n\alpha)$




$\sigma$  vs. E for  $^{66}\text{Cu}(n,2n\alpha)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{66}\text{Cu}(n,np)$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{nd})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{nd})$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,nt)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{66}\text{Cu}(n,nt)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,2np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{66}\text{Cu}(n,2np)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n_1)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{66}\text{Cu}(n,n_1)$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n_1)$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n_1)$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n_1)$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n_1)$




Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abcissa scales are energy (eV).




$\sigma$  vs.  $E$  for  $^{66}\text{Cu}(n,n_2)$




Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).




$\sigma$  vs.  $E$  for  $^{66}\text{Cu}(n,n_3)$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).





Correlation Matrix









$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,n\text{cont.})$





Correlation Matrix









$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,ncont.)$



Correlation Matrix










Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix









$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,d)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{66}\text{Cu}(n,d)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,t)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{66}\text{Cu}(n,t)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{He3})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{66}\text{Cu}(n,\text{He3})$




$10^7$





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{66}\text{Cu}(n,p\alpha)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{66}\text{Cu}(n,p\alpha)$



$10^7$



Correlation Matrix

