




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{tot.})$





Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$




$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{el.})$





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{nonel.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{inel.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{inel.})$





$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{ncont.})$

10^7



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{inel.})$




$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\gamma)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{60}\text{Fe}(n,2n)$





Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,n_1)$




$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,p)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,3n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{60}\text{Fe}(n,3n)$



10^7

10^{-5}

10^{-4}


10^{-3}

10^{-2}

10^{-1}

Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,2n\alpha)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{60}\text{Fe}(n,2n\alpha)$



10^7


10^{-15}

0 5 10 15 20 25 30

Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{60}\text{Fe}(n,np)$



10^7

10^{-10}

10^{-8}

10^{-6}

10^{-4}

10^{-2}

Correlation Matrix



1.0

0.8

0.6

0.4

0.2

0.0

-1.0

-0.8


-0.6

-0.4

-0.2

0.0

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,\text{nd})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{60}\text{Fe}(n,\text{nd})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,n\text{cont.})$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{60}\text{Fe}(n,d)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{60}\text{Fe}(n,d)$



10^7

10^{-2}

10^{-4}

10^{-6}


10^{-8}

10^{-10}

10^7


10^8

Correlation Matrix



1.0
0.8
0.6
0.4
0.2
0.0


-1.0
-0.8
-0.6
-0.4
-0.2
0.0




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.




σ vs. E for $^{60}\text{Fe}(n,t)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix

