




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{tot.})$





Correlation Matrix





Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Ordinate scale is %  
relative standard deviation.





Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{tot.})$




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{tot.})$




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,p)$



Ordinate scale is %  
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{tot.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix










Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{el.})$







$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Ordinate scale is %  
relative standard deviation.





Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{el.})$




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{el.})$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,p)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,el.)$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{el.})$





Correlation Matrix









Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix






$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{nonel.})$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,p)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{nonel.})$





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Ordinate scale is %  
relative standard deviation.





Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{inel.})$




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{inel.})$




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,p)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\text{inel.})$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n_1)$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %  
relative standard deviation.

Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,\gamma)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,p)$



Ordinate scale is %  
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n)$




Correlation Matrix






$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,3n)$




$\sigma$  vs. E for  $^{60}\text{Fe}(n,3n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n\alpha)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{60}\text{Fe}(n,n\alpha)$




Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,2n\alpha)$




$\sigma$  vs. E for  $^{60}\text{Fe}(n,2n\alpha)$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{60}\text{Fe}(n,np)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,nd)$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{60}\text{Fe}(n,nd)$





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n_{\text{cont}})$ .



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n, n_1)$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n_1)$



Correlation Matrix














Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).









Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n\text{cont.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{60}\text{Fe}(n,n\text{cont.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,p)$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,ncont.)$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,n\text{cont.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,p)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{60}\text{Fe}(n,p)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,d)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{60}\text{Fe}(n,d)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{60}\text{Fe}(n,t)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{60}\text{Fe}(n,t)$




$10^7$



Correlation Matrix





Ordinate scales are % relative standard deviation and barns.  
 Abscissa scales are energy (eV).

