




Ordinate scales are % relative standard deviation and barns.
 Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix






$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$


Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,el.)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n\text{onel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{incl.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{inel.})$





Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n\text{cont.})$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,p)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,3n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,3n)$




10^7

$\times 10^6$

0 2 4 6 8 10 12 14 16

Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,2n\alpha)$



10⁷

10⁻⁷


10⁻⁹

10⁻¹¹


10⁻¹³

10⁻¹⁵

Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,np)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{57}\text{Fe}(n,np)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,\text{nd})$



10^7


10^{-4}

10^{-6}


10^{-8}

10^{-10}

Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,nt)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,nt)$



10^7

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7


0 20 40 60 80 100 120 140

10^{-18}

0 20 40 60 80 100 120 140

10^7

$\Delta\sigma/\sigma$ vs. E for ^{57}Fe (mt 34)



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for ^{57}Fe (mt 34)



10^7

$\times 10^{-18}$

0

200

400


600

800


1000

1200

Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2np)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,2np)$




10^7



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,\gamma)$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\gamma)$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,t)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{57}\text{Fe}(n,t)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{He}3)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,\text{He}3)$



10^7

10^{-5}

10^{-7}


10^{-9}

10^{-11}

10^{-13}

Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{57}\text{Fe}(n,\alpha)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,p\alpha)$





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{57}\text{Fe}(n,p\alpha)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,pd)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{57}\text{Fe}(n,pd)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{pt})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,\text{pt})$



Correlation Matrix

