


MAT 9919

Energy Release
Heating - Damage


99-Es-254




MAT 9919

Inelastic Radionuclide Production Cross Section


99-Es-254




Radionuclide Production Cross Section




Radionuclide Production Cross Section




Radionuclide Production Cross Section




Radionuclide Production Cross Section




Radionuclide Production Cross Section







Radionuclide Production Cross Section





Radionuclide Production Cross Section



Radionuclide Production Cross Section







Radionuclide Production Cross Section

