




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{inel.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{tot.})$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{tot.})$




$10^7$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).




Warning: some uncertainty  
data were suppressed.





Correlation Matrix











Correlation Matrix



Ordinate scale is %  
relative standard deviation.



Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{inel.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.




Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.




Correlation Matrix









Correlation Matrix











Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).



Warning: some uncertainty data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix









Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{inel.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{nonel.})$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{nonel.})$









$10^7$






Correlation Matrix















Ordinate scale is %  
relative standard deviation.




Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{inel.})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{inel.})$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{inel.})$




$10^7$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.





Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix








Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix








Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,n_1)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\gamma)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,p)$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\alpha)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n)$




Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\alpha)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{55}\text{Fe}(n,\alpha)$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2n\alpha)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{55}\text{Fe}(n,2n\alpha)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{nd})$




10<sup>7</sup>



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,2np)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{55}\text{Fe}(n,2np)$




$10^7$

$10^9$

Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}$ (mt 45)



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{55}\text{Fe}$ (mt 45)



Correlation Matrix






Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,n_4)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{55}\text{Fe}(n,n_4)$





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.







$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,p)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,ncont.)$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.





Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.




$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,p)$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,d)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




Correlation Matrix



$\sigma$  vs. E for  $^{55}\text{Fe}(n,d)$









Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{He3})$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{He3})$



Correlation Matrix






Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{pd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{pd})$



$10^7$


$10^{-14}$

$10^{-12}$

$10^{-8}$

$10^{-6}$

Correlation Matrix



1.0

0.8

0.6

0.4

0.2

0.0

-1.0

-0.8


-0.6

-0.4

-0.2

0.0

$\Delta\sigma/\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{pt})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{55}\text{Fe}(n,\text{pt})$



10<sup>7</sup>

10<sup>-17</sup>

10<sup>-15</sup>

10<sup>-13</sup>

10<sup>-11</sup>

10<sup>-9</sup>

Correlation Matrix

