



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{el.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{tot.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{tot.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abcissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{el.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.





Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix









Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{el.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{el.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abcissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abcissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{nonel.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{inel.})$



Correlation Matrix









Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{inel.})$





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abcissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,n_1)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\gamma)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,2n)$





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\alpha)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,2n)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,2n\alpha)$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{55}\text{Fe}(n,2n\alpha)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{55}\text{Fe}(n,np)$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,2np)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{55}\text{Fe}(n,2np)$




10⁷



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for ^{55}Fe (mt 45)



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for ^{55}Fe (mt 45)





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\gamma)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,n_1)$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\gamma)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,n\text{cont.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,n\text{cont.})$





Correlation Matrix






$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,n\text{cont.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\gamma)$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{55}\text{Fe}(n,\gamma)$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\gamma)$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\gamma)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{55}\text{Fe}(n,p)$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,p)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.




σ vs. E for $^{55}\text{Fe}(n,t)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{55}\text{Fe}(n,\alpha)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,pd)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{55}\text{Fe}(n,pd)$



10^7

10^{-14}
 10^{-12}
 10^{-10}
 10^{-8}
 10^{-6}


Correlation Matrix



1.0
0.8
0.6
0.4
0.2
0.0

-1.0
-0.8
-0.6
-0.4
-0.2
0.0

$\Delta\sigma/\sigma$ vs. E for $^{55}\text{Fe}(n,\text{pt})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{55}\text{Fe}(n,\text{pt})$



10^7

10^{-9}

10^{-11}

10^{-13}

10^{-15}

10^{-17}

Correlation Matrix



1.0
0.8
0.6
0.4
0.2
0.0

-1.0
-0.8
-0.6
-0.4
-0.2
0.0