




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{nonel.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{tot.})$





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{tot.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{nonel.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{el.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{el.})$







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{nonel.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{58}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{nonel.})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{nonel.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{58}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,n_1)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,p)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\alpha)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,2n)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,3n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{58}\text{Fe}(n,3n)$




10^7



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,np)$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{58}\text{Fe}(n,np)$




10^7

10^7




Correlation Matrix



-1.0
-0.8
-0.6
-0.4
-0.2
0.0

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{58}\text{Fe}(n,\text{nd})$




10^7



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,nt)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{58}\text{Fe}(n,nt)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,n_1)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,n_1)$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\gamma)$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.




σ vs. E for $^{58}\text{Fe}(n,d)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.




σ vs. E for $^{58}\text{Fe}(n,t)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,\text{He}3)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{58}\text{Fe}(n,\text{He}3)$



10^7

10^{-9}

10^{-10}

10^{-11}

10^{-12}

10^{-13}

Correlation Matrix



1.0

0.8

0.6

0.4

0.2

0.0

-1.0


-0.8

-0.6

-0.4


-0.2

0.0




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).




σ vs. E for $^{58}\text{Fe}(n,\alpha)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,p\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{58}\text{Fe}(n,p\alpha)$



10^7

10^{-20}
 10^{-18}
 10^{-16}
 10^{-14}
 10^{-12}


Correlation Matrix



1.0
0.8
0.6
0.4
0.2
0.0

-1.0
-0.8
-0.6
-0.4
-0.2
0.0

$\Delta\sigma/\sigma$ vs. E for $^{58}\text{Fe}(n,pd)$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{58}\text{Fe}(n,pd)$



10^7

10^7



Correlation Matrix

