



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$





Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{tot.})$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix








Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$





Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$



Correlation Matrix








Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{el.})$




Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n\text{onel.})$







Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nonel.})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{inel.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,\text{inel.})$





Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abcissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{inel.})$



Correlation Matrix









Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{57}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n_1)$





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\gamma)$





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,p)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n)$



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,3n)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,3n)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




σ vs. E for $^{57}\text{Fe}(n,n\alpha)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2n\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,2n\alpha)$





10^7


10^7



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,np)$





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{57}\text{Fe}(n,np)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,\text{nd})$



10^7

10^{-8}


10^{-7}

10^{-6}


10^{-5}

10^{-4}

Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,nt)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{57}\text{Fe}(n,nt)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for ^{57}Fe (mt 34)




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for ^{57}Fe (mt 34)



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,2np)$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,2np)$




10^7

10^9



Correlation Matrix



1.0

0.8

0.6

0.4

0.2

0.0

-1.0


-0.8

-0.6

-0.4

-0.2



0.0




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.





Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix










Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,n_1)$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix








Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix








Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix








Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,\gamma)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\gamma)$



Correlation Matrix








Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




σ vs. E for $^{57}\text{Fe}(n,p)$



Correlation Matrix








Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




σ vs. E for $^{57}\text{Fe}(n,d)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,t)$





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{57}\text{Fe}(n,t)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{He3})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,\text{He3})$



10^7

10^{-13}

10^{-5}


10^{-7}


10^{-9}

10^{-11}

10^{-13}

Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{57}\text{Fe}(n,\alpha)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,p\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{57}\text{Fe}(n,p\alpha)$



10^7

10^{-6}


10^{-8}

10^{-10}

10^{-12}

10^{-14}

Correlation Matrix



1.0

0.8

0.6

0.4

0.2

0.0

-1.0

-0.8


-0.6

-0.4

-0.2

0.0

$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,pd)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{57}\text{Fe}(n,pd)$




10^7

10^{-18}

Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{57}\text{Fe}(n,\text{pt})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{57}\text{Fe}(n,\text{pt})$



Correlation Matrix

