




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\alpha)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{tot.})$





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{el.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\alpha)$





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\alpha)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{inel.})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{71}\text{Ge}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{inel.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{inel.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{inel.})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{71}\text{Ge}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,n_1)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\gamma)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,p)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\alpha)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,3n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{71}\text{Ge}(n,3n)$




*10⁹

180

200
180
160
140
120
100
80
60
40
20
0

10^7




Correlation Matrix



1.0
0.8
0.6
0.4
0.2
0.0

-1.0
-0.8
-0.6
-0.4
-0.2
0.0

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,n\alpha)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{71}\text{Ge}(n,n\alpha)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2n\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{71}\text{Ge}(n,2n\alpha)$



4.0
3.5
3.0
2.5
2.0
1.5
1.0
0.5
0.0


10^7



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{71}\text{Ge}(n,np)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{71}\text{Ge}(n,\text{nd})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,nt)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{71}\text{Ge}(n,nt)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for ^{71}Ge (mt 34)



Ordinate scales are % relative standard deviation and barns.

Abcissa scales are energy (eV).

σ vs. E for ^{71}Ge (mt 34)



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,2np)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{71}\text{Ge}(n,2np)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for ^{71}Ge (mt 45)



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for ^{71}Ge (mt 45)



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,n_1)$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,n_1)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{71}\text{Ge}(n,n_4)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\alpha)$





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\gamma)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\alpha)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,p)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,d)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{71}\text{Ge}(n,d)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,t)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{71}\text{Ge}(n,t)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{He3})$




Ordinate scales are % relative standard deviation and barns.



Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{71}\text{Ge}(n,\text{He3})$




σ vs. E for $^{71}\text{Ge}(n,\text{He3})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



σ vs. E for $^{71}\text{Ge}(n,\alpha)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,p\alpha)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{71}\text{Ge}(n,p\alpha)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{pd})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{71}\text{Ge}(n,\text{pd})$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(n,\text{pt})$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{71}\text{Ge}(n,\text{pt})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{71}\text{Ge}(\text{mt117})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{71}\text{Ge}(\text{mt117})$



Correlation Matrix

