





$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n,tot.})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

Correlation Matrix





Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,2n)$

Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,\text{tot.})$




Correlation Matrix








Correlation Matrix





Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).



Correlation Matrix



Ordinate scale is % relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty data were suppressed.





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

Correlation Matrix






Correlation Matrix





Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

Correlation Matrix





Correlation Matrix






$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,2n)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,\text{el.})$










Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

Correlation Matrix






Ordinate scale is % relative standard deviation.



Abscissa scales are energy (eV).
Warning: some uncertainty data were suppressed.

Correlation Matrix







Correlation Matrix



Ordinate scales are % relative standard deviation and barns.
Abscissa scales are energy (eV).
Warning: some uncertainty data were suppressed.



Correlation Matrix




Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,2n)$


Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,\text{nonel.})$




Correlation Matrix







Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.








Ordinate scale is % relative standard deviation.


Abscissa scales are energy (eV).
Warning: some uncertainty data were suppressed.

Correlation Matrix





Correlation Matrix



Ordinate scale is % relative standard deviation.



Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n,inel.})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,2n)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,\text{ncont.})$


Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,\gamma)$

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

60
50
40
30
20
10
0


10^7




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,2n)$

50
40
30
20
10
0

10^7

Correlation Matrix






$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,\alpha)$

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,\text{n}\alpha)$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{26}\text{Al}(n,\text{n}\alpha)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n},\text{np})$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{26}\text{Al}(\text{n},\text{np})$




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n},\text{nd})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{mt 34})$

3.0
2.5
2.0
1.5
1.0
0.5
0.0




Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n},2\text{np})$

Ordinate scales are % relative
standard deviation and barns.


Abscissa scales are energy (eV).



σ vs. E for $^{26}\text{Al}(\text{n},2\text{np})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{mt } 45)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,n_2)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,n_3)$

Ordinate scales are % relative
standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{26}\text{Al}(n,n_3)$




Correlation Matrix








Ordinate scales are % relative
standard deviation and barns.
Abscissa scales are energy (eV).





Correlation Matrix






Correlation Matrix






Correlation Matrix




Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).



Warning: some uncertainty
data were suppressed.






Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).






Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(n,\gamma)$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.





Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.







Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty data were suppressed.


Correlation Matrix








Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix









Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.


Correlation Matrix







Ordinate scales are % relative
standard deviation and barns.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n},\text{He3})$

30
25
20
15
10
5
0


10^7


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix






Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n},\text{p}\alpha)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n},\text{pd})$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{n},\text{pt})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{26}\text{Al}(\text{mt117})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix

