





Ordinate scales are % relative
standard deviation and barns.
Abscissa scales are energy (eV).



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.


Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,2n)$



Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\text{tot.})$




Correlation Matrix






Correlation Matrix




Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(\text{n,tot.})$

Correlation Matrix






Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.





Correlation Matrix






Correlation Matrix











Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




Correlation Matrix





Correlation Matrix




Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\text{el.})$




Correlation Matrix







Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix








Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix








Ordinate scale is % relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.







Correlation Matrix




Ordinate scale is % relative standard deviation.



Abscissa scales are energy (eV).



Ordinate scales are % relative standard deviation and barns.
 Abscissa scales are energy (eV).
 Warning: some uncertainty data were suppressed.

Correlation Matrix







Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,2n)$



Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




Correlation Matrix





Correlation Matrix




Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(\text{n,inel.})$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,2n)$



Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\text{inel.})$



Correlation Matrix










Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




Correlation Matrix






Correlation Matrix







Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.









Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).



Correlation Matrix






$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,n_1)$


Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,2n)$



Correlation Matrix







$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\gamma)$

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.





Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,p)$

Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\alpha)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,2n)$





Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,3n)$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix






$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\text{np})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\text{nd})$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\text{nt})$

* 10^{-3}
25
20
15
10
5
0
 10^7

Ordinate scales are % relative
standard deviation and barns.
Abscissa scales are energy (eV).



Correlation Matrix







$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,n_1)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




Correlation Matrix






Correlation Matrix





Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.







Ordinate scale is % relative standard deviation.



Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.





Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,n_2)$

Ordinate scales are % relative
standard deviation and barns.



Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.
Abscissa scales are energy (eV).









Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

Correlation Matrix






Correlation Matrix





Ordinate scale is % relative standard deviation.


Abscissa scales are energy (eV).



Warning: some uncertainty data were suppressed.





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,\gamma)$


Ordinate scales are % relative
standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,p)$


Ordinate scales are % relative
standard deviation and barns.



Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(n,t)$

10²
10¹
10⁰
10⁻¹
10⁷


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.


10⁻³
10⁻⁵
10⁻⁷
10⁻⁹
10⁻¹¹
10⁷


σ vs. E for $^{62}\text{Ni}(n,t)$




Correlation Matrix







Ordinate scales are % relative
standard deviation and barns.
Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{62}\text{Ni}(\text{n},\text{p}\alpha)$

10¹
10⁰
10⁻¹
10⁷

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix

