






Ordinate scales are % relative
standard deviation and barns.
Abscissa scales are energy (eV).







Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).

Correlation Matrix






Correlation Matrix




Ordinate scale is % relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty data were suppressed.



Correlation Matrix




Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).



$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,2n)$


25
20
15
10
5
0




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{tot.})$





Correlation Matrix







Correlation Matrix



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Warning: some uncertainty
data were suppressed.



Correlation Matrix



Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).





Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$


Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{tot.})$



Correlation Matrix










Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.





Correlation Matrix





Correlation Matrix




Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,2n)$

Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{el.})$




Correlation Matrix







Correlation Matrix




Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.








Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).



Correlation Matrix








Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

Correlation Matrix






Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix






Warning: some uncertainty
data were suppressed.


Ordinate scales are % relative
standard deviation and barns.

Correlation Matrix







Correlation Matrix



Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{nonel.})$





Correlation Matrix






Correlation Matrix




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.




Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).




Correlation Matrix









Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(\text{n,inel.})$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{66}\text{Ni}(\text{n,inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,2n)$


Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.




Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).





Correlation Matrix





Correlation Matrix



Ordinate scale is % relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,p)$


Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{inel.})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$

Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{inel.})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,2n)$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{66}\text{Ni}(n,2n)$




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,n_1)$


Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix










Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,3n)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{n}\alpha)$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



σ vs. E for $^{66}\text{Ni}(n,\text{n}\alpha)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{np})$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\text{nt})$


* 10^{-12}
70
50
40
30
20
10
0

Abscissa scales are energy (eV).
Ordinate scales are % relative standard deviation and barns.




Correlation Matrix








Ordinate scales are % relative
standard deviation and barns.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.





Correlation Matrix






Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.






Correlation Matrix





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$

Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,n_1)$




Correlation Matrix








Ordinate scales are % relative
standard deviation and barns.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,n_4)$


Ordinate scales are % relative
standard deviation and barns.




Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.





Correlation Matrix










Ordinate scale is %
relative standard deviation.
Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$


Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,n\text{cont.})$




Correlation Matrix







Correlation Matrix



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,p)$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$

Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,d)$


Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,t)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(\text{n},\text{He3})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{66}\text{Ni}(n,\alpha)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix

