






Ordinate scale is %
relative standard deviation.

Warning: some uncertainty
data were suppressed.




Correlation Matrix






Correlation Matrix



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.






Correlation Matrix














Ordinate scale is % relative standard deviation.


Warning: some uncertainty
data were suppressed.



Correlation Matrix













Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

Correlation Matrix













Ordinate scales are % relative standard deviation and barns.

Warning: some uncertainty
data were suppressed.



Correlation Matrix






$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,2n)$


Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,n_1)$


Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,\text{nonel.})$




Correlation Matrix






Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.





















Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.













Ordinate scales are % relative
standard deviation and barns.


Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.





σ vs. E for $^{25}\text{Al}(n,2n)$

Correlation Matrix









$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,\text{nd})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(\text{mt 34})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,2\text{np})$


Ordinate scales are % relative
standard deviation and barns.


Abscissa scales are energy (eV).





Correlation Matrix











Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.


Correlation Matrix



























Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.


Correlation Matrix








Correlation Matrix
















$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,t)$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(\text{n},\text{He3})$


Ordinate scales are % relative
standard deviation and barns.



Abscissa scales are energy (eV).
Warning: some uncertainty
data were suppressed.



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,\text{pd})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(n,\text{pt})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{25}\text{Al}(\text{mt117})$

Ordinate scales are % relative
standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix

