




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{nonel.})$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$




Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,n\text{cont.})$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{nonel.})$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{el.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{el.})$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.








Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{nonel.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).




Correlation Matrix



$\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{nonel.})$







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$



Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{nonel.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,n\text{cont.})$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.




$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{nonel.})$



Correlation Matrix








Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix








Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,n_1)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,n\text{cont.})$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\gamma)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$




Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,p)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\alpha)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2n)$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\alpha)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




Correlation Matrix



$\sigma$  vs. E for  $^{52}\text{Fe}(n,\alpha)$







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{nd})$




$10^7$

$10^9$

Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,nt)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{52}\text{Fe}(n,nt)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}$ (mt 34)




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{52}\text{Fe}$ (mt 34)



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,2np)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{52}\text{Fe}(n,2np)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}$ (mt 45)




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{52}\text{Fe}$ (mt 45)




$10^7$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.




Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\alpha)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix









Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,p)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,ncont.)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\alpha)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,ncont.)$



Correlation Matrix






Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,t)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




Correlation Matrix



$\sigma$  vs. E for  $^{52}\text{Fe}(n,t)$




$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{He3})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




Correlation Matrix



$\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{He3})$




$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\alpha)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




Correlation Matrix



$\sigma$  vs. E for  $^{52}\text{Fe}(n,\alpha)$







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{pd})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{pd})$



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{pt})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{52}\text{Fe}(n,\text{pt})$




$10^7$

$10^8$

Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{52}\text{Fe}(\text{mt117})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{52}\text{Fe}(\text{mt117})$



Correlation Matrix

