



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{el.})$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{inel.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,n\text{cont.})$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.



Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{el.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{inel.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{el.})$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{inel.})$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,n\text{cont.})$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{nonel.})$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.




Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{inel.})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,n\text{cont.})$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{inel.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix








Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).




Correlation Matrix



$\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,n\text{cont.})$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\gamma)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,p)$



Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\alpha)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n)$




Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,3n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{61}\text{Ni}(n,3n)$




$10^7$

$10^9$

Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\alpha)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




Correlation Matrix



$\sigma$  vs. E for  $^{61}\text{Ni}(n,\alpha)$



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2n\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{61}\text{Ni}(n,2n\alpha)$



$10^7$


$10^{-7}$

$10^{-9}$

$10^{-11}$

$10^{-13}$

Correlation Matrix



1.0

0.8

0.6

0.4

0.2

0.0

-1.0

-0.8


-0.6

-0.4

-0.2

0.0


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Ni}(n,np)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{nd})$




$10^7$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,nt)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Ni}(n,nt)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,2np)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{61}\text{Ni}(n,2np)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix








Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



$\sigma$  vs.  $E$  for  $^{61}\text{Ni}(n,n\text{cont.})$




Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\gamma)$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,n\text{cont.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix









Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{He}3)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{He}3)$




$10^7$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,p\alpha)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{61}\text{Ni}(n,p\alpha)$




$10^7$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{pd})$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{pd})$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{pt})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{61}\text{Ni}(n,\text{pt})$



$10^7$

$10^{-18}$

$10^{-16}$

$10^{-14}$

$10^{-12}$

$10^{-10}$

Correlation Matrix

