




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{nonel.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$





Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{tot.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{el.})$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{el.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.
 Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{nonel.})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$



Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{nonel.})$




Correlation Matrix







$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{inel.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,\text{inel.})$




Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$






$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$




Correlation Matrix







$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\gamma)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{inel.})$




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$




σ vs. E for $^{70}\text{Ge}(n,2n)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n_1)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\gamma)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,p)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\alpha)$



Ordinate scale is %
relative standard deviation.

Abcissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,n\alpha)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2n\alpha)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,2n\alpha)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,np)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{nd})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,\text{nd})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,nt)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{70}\text{Ge}(n,nt)$




10^7



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,2np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,2np)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for ^{70}Ge (mt 45)



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for ^{70}Ge (mt 45)



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n_1)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,n_1)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n_{\text{cont}})$



Ordinate scale is %
relative standard deviation.





Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n_1)$



Correlation Matrix









Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n_1)$





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n_2)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,n_2)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n_3)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,n_3)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n_4)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,n_4)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\gamma)$




Ordinate scale is %
relative standard deviation.





Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$




Correlation Matrix







$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\alpha)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,n\text{cont.})$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\gamma)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{70}\text{Ge}(n,p)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,d)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

σ vs. E for $^{70}\text{Ge}(n,d)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,t)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{70}\text{Ge}(n,t)$




10^7



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{He3})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




Correlation Matrix





σ vs. E for $^{70}\text{Ge}(n,\text{He3})$





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,p\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.




Correlation Matrix



σ vs. E for $^{70}\text{Ge}(n,p\alpha)$




$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(n,\text{pd})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{70}\text{Ge}(n,\text{pd})$




10^7



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{70}\text{Ge}(\text{mt117})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{70}\text{Ge}(\text{mt117})$



Correlation Matrix

